



TERCENAS BRIDGE

A chloride induced corrosion case

Luís Oliveira Santos



Location



Location




Tercenas Bridge



Owner.....Office of Water Services
Construction.....1970



Tercenas Bridge







Jacinto, L. (2011). *Safety assessment of existing bridges. Bayesian Probabilistic Approach*, PhD thesis, FCT/UNL.
<http://run.unl.pt/handle/10362/7601>.

Visual inspection

Minor damages

Sep. 2004



Visual inspection Structural damages

- Cracking
- Concrete delamination
- Corrosion of reinforcement bars



On-site tests

In areas without apparent degradation of the concrete:


- Determination of concrete cover depth
- Measurement of carbonation depth
- Measurement of corrosion potential (ASTM C876:91)
- Measurement of corrosion rate (RILEM TC-154-EMC, 2002)
- Measurement of resistivity of concrete

Measurements at Beams 1, 2 & 4; South pier; South Abutment

Manuel Salta *et al.* (2005).

On-site tests


Corrosion potential, corrosion current & resistivity of concrete



Icorr - Corrosion current ($\mu\text{A cm}^{-2}$)	Probability of corrosion	Symbology
E - Corrosion potential (mV)	90 %	
R - Resistivity of concrete ($\text{k}\Omega$)	10-90%	
	10%	

On-site tests

Corrosion potential, corrosion current & resistivity of concrete



South pier

Manuel Salta et al . (2005).

Laboratory tests

Taking cores for testing:


- Chloride content of concrete
- Carbonation of concrete
- Compressive strength of concrete
- Microscopic analysis



Laboratory tests

Chloride penetration profile



Nov./Dec. 2004



Laboratory tests

Microscopic analysis

Nov./Dec. 2004



Element	Ca	O	Al	Si	Na	K
Content(%)	17	42		30	4	9

Conclusions and recommendations from the tests

Taking into account:

- The advanced state of degradation of the bridge
- The very depth contamination of concrete with chlorides.

Bridge replacement was recommended.

Safety until replacement ?

- Traffic restrictions
 - Speed limit
 - Maximum weight
 - Avoid traffic over the left beam
- Frequent visual inspections



Traffic restrictions

Bridge visual inspection

Structural damages

Jan. 2008



Bridge visual inspection

Structural damages

April 2009



Bridge visual inspection

Structural damages

March/Dec. 2011




March 2011



Dec 2011

Safety until replacement ?

- According to the Portuguese national code: NO
- Target reliability index, $\beta_T=3,8$
- The mid-span section of beam 4 was critical (bars residual section).
- A probabilistic analysis with Bayesian updating was carried out: the value of $\beta_T=3,9$ achieved showed that the risk of failure of the bridge could be considered acceptable for the time needed for bridge replacement



Bridge demolition

2012



New Tercenas Bridge

2014



Is this case study valuable for Vol analysis ?

Pros

- Strongly damaged concrete bridge
- Chloride induced corrosion
- Relevant data available: visual inspections, on-site & laboratory tests

Cons

- No use of SHM
- Bridge already replaced