


VOI related to composite patch reparations

Dr. Ander Zornoza
Dr. Elena Rodríguez
Rubén de la Mano

Robotics and Control + Advanced materials
units



aimen
CENTRO TECNOLÓGICO

Collaborative Project. Call ID FP7-SST-2008-RTD-1- Proposal N° 233969. Duration: 40 Months (2010 – 2013)

PROJECT PARTICIPANTS




Table of contents

- INTRODUCTION
- FBG STRAIN SENSORS
- EXPERIMENTAL RESULTS
- VALUE OF INFORMATION (VOI)



Table of contents





- INTRODUCTION
- FBG STRAIN SENSORS
- EXPERIMENTAL RESULTS
- VALUE OF INFORMATION (VOI)



COPATCH CONCEPT

Repairing the damaged structure by a bonded composite patch


Damage: crack or corrosion



COPATCH solution works **transferring the stress** from the damaged steel to the composite patch **through the adhesive layer**. It allows **to recover** the integrity of the damaged steel to **its original state**.

Homogeneous load transfer

COPATCH CONCEPT



ADVANTAGES OF THE COMPOSITE PATCH REPAIR


Conventional solution in shipbuilding: replacement of the damaged steel sheet (cutting and welding) or double sheet welding.

Disadvantages of the conventional solution:

- ✓ **Temperature:** thermal treatment distortions
- ✓ Residual stress
- ✓ Weight increase
- ✓ Harmful environment work (particles, fumes, smokes)
- ✓ Necessity of grounding
- ✓ At explosive environments: Need of emptying and cleaning of tanks
- ✓ Large working hours and high labor costs



www.distorsioncero.es




ADVANTAGES OF THE COMPOSITE PATCH REPAIR

Conventional solution in shipbuilding: replacement of the damaged steel sheet (cutting and welding) or double sheet welding.

Main advantages of COPATCH solution:

- ✓ Low (almost environment) temperatures
- ✓ “In situ” application
- ✓ Low added weight – low weight materials – cranes are not necessary to move the material
- ✓ No stress concentrations – good fatigue behavior
- ✓ Good durability – less corrosion
- ✓ Easy to perform



BACKGROUND – COMPOSITE PATCH REPAIR

Composite patches have been applied successfully on civil constructions, on naval ships (military), aircraft, pipe works and offshore platforms :



The Royal Australian Navy. Adelaide Class Frigate
Repair of the main deck

www.compclass.org.uk



FPSO (Floating Production Storage and Offloading) - Norway
Repair of the cargo tank bulkhead



West Gate Bridge, Melbourne, 2012



ISO/TS 24817:2006: Petroleum, petrochemical and natural gas industries -- Composite repairs for pipework -- Qualification and design, installation, testing and inspection

BACKGROUND – COMPOSITE PATCH REPAIR

COPATCH CHALLENGE

SPECIAL FEATURES OF COMPOSITE REPAIR IN SHIPBUILDING

- Material: conventional steel (grade A)
- Thickness: 6 - 20 mm
- Classification Society Approval

Control of patch repairs
FBGs Monitoring




Table of contents

- INTRODUCTION
- FBG STRAIN SENSORS
- EXPERIMENTAL RESULTS
- VALUE OF INFORMATION (VOI)




Advantages of FBG Strain Sensors

- ✓ Small **size** and weight
- ✓ **Multiplexing** and **multifunctionality**
- ✓ Highly **sensitive** and precise
- ✓ Excellent performance in **harsh environments** with long term stability
- ✓ modular equipment
- ✓ **Absolute measurements** without referencing
- ✓ Suitable for **hard-to-reach locations**
- ✓ **Immunity** to electromagnetic and radio frequency interferences
- ✓ Packaging suitable for various applications (laboratory, outdoor, concrete...) and large scale sensing networks.
- ✓ Ideal for remote **monitoring**



FBG Strain Sensors to monitor bonded composite patch repairs

Failure modes of a composite patch repair:




FBGs can monitor:



1. Steel crack growth (patch side or back side)
2. Composite debonding (adhesive layer)
3. Internal composite failure

FBG Strain Sensors to monitor bonded composite patch repairs

Mid-scale tests specimen



Back side steel monitoring



Composite laminate monitoring (Embedded FBGs)



Adhesive layer monitoring



Mid-scale specimen - Static Tensile tests

Comparative study: Conventional strain gages vs FBGs measurements

FBGs (FA, FB) and strain gages (GA, GB) bonded in steel and one strain gage bonded in the top of the patch (GC)





Table of contents


- INTRODUCTION
- FBG STRAIN SENSORS
- EXPERIMENTAL RESULTS
- VALUE OF INFORMATION (VOI)



Mid-scale specimen - Static Tensile tests

Preliminary tests to select patch materials and steel surface treatment

Global Load vs Displacement curve. FAILURE: patch debonding.



Patch effectiveness:
greatly increase the stiffness of the structure and the maximum load


	Max load
Unpatched	125 kN
Patched	260 kN

Best results:



- ✓ Grit blasting surface treatment
- ✓ Hand lay-up manufacturing
- ✓ Vinyl ester
- ✓ Carbon fiber, unidirectional

Mid-scale specimen - Static Tensile tests

Comparative study: Conventional strain gages vs FBGs measurements




FBGs same behavior than conventional gages





Mid-scale specimen - Cycled Tensile tests

A, B: adhesive layer
C: steel (back side)


Good patch adhesion



Full-scale test - CATAMARAN steel structure monitoring



Vigo sea inlet





Shipbuilder
CARDAMA



Full-scale test - CATAMARAN steel structure monitoring


Fatigue cycle (bending): filling up/emptying the upper tank




Full-scale test - CATAMARAN steel structure monitoring

FBG Monitoring of:

- ✓ 3 types of cracks
- ✓ In different frames
- ✓ Patched and unpatched



1. 45°, length=100mm



2. Vertical, length= 40mm




3. 45°, length=60mm





Full-scale test - CATAMARAN steel structure monitoring

Patched: 3 FBGs



Unpatched: 1 FBGs




Full-scale test - CATAMARAN steel structure monitoring




Full-scale test - CATAMARAN steel structure monitoring



Full-scale test - CATAMARAN steel structure monitoring




Full-scale test - CATAMARAN steel structure monitoring



After 20.000 cycles neither patch debonding nor crack growth have been observed

July '12

→ May '13



- Premature FBG's debonding was detected because of the action of the corrosion.
- Protective paint should be applied in whole area where the FBGs are bonded to avoid corrosive processes that damage the fiber.





Table of contents

- INTRODUCTION
- FBG STRAIN SENSORS
- EXPERIMENTAL RESULTS
- VALUE OF INFORMATION (VOI)
- CONCLUSIONS




- FBG monitoring gives information of the reparation and **defects can be detected**: debonding and crack growth
- Patch material and application **techniques have been optimized during co-patch project and failure reduced**: no defects in 20.000 cycles of fatigue in a full scale demonstrator catamaran
- **Codes, Flag administrations and Classification society do not include composite patch reparations**
- Additional inspections and approvals (plan reviews) are needed to compile for approvals by Classification Society – they are expensive
 - Monitoring with FBGs could accelerate inclusion of patch reparations in codes – we have the **adequate tool to evaluate and feed models with experimental data**
- VOI will be related **tradeoff between ship downtime, reparation costs (+plan review?), maintenance cost of reparation and failure/defect probability**

Thank you!

Acknowledgments

The research leading to these results has received funding from the European Union's Seventh Framework Programme (FP7/2007-2013) under grant agreement No. 233969.

Astilleros Cardama and *Estaleiros Navais de Peniche* in the specimens manufacturing and full-scale tests.



aimen
CENTRO TECNOLÓGICO

Ander.zornoza@aimen.es