

Health Monitoring of Bridges Applied to the Halic Metro Bridge in Istanbul

Helmut WENZEL

September 2015, Istanbul


































Halic Metro Bridge Construction








Halic Metro Bridge Construction








Halic Metro Bridge Construction




Current Status

- The monitoring system is in place and running since February 2014
- It is a typical Structural Health Monitoring System (not a strong motion station or a scientific experiment)
- VCE took care of fine tuning for 1 year (ended in February 2015)
- System operation by Municipality






Monitoring Facts and Figures




South-West































3rd Bosphorus Bridge LOCATION



3rd Bosphorus Bridge LOCATION



3rd Bosporus Bridge Monitoring




3rd Bosporus Bridge Monitoring

European Side




3rd Bosporus Bridge

Construction Stage Monitoring



3rd Bosporus Bridge

Construction and Monitoring



3rd Bosporus Bridge

Construction and Monitoring



Izmit Bay Bridge / Gebze – Izmir Motorway Project

Construction Activities 2014 – 2015













Catwalk System








Transition Span – Deck Erection South (TS08~TS03)
ACTUAL FINISH: 18-JULY-2015

Cable Strand Installation



IHI Infrastructure Systems Co., Ltd.



Cable Strand Installation

ACTUAL START: 7-SEP-2015